



NOTE: FITTINGS SHALL BE FLARED END CONNECTIONS FOR 1" COPPER AND SWEAT BY THREADED FOR 2" COPPER. ( MIP X FIP 2" CORP )

- ① DOUBLE STRAP BRONZE SERVICE SADDLE ON A.C. PIPE  
BRONZE OR BRASS SADDLE WITH STAINLESS STEEL FOUR BOLT STRAPS FOR PVC
- ② BRONZE CORPORATION STOP
- ③ TYPE K COPPER (ONE CONTINUOUS PIECE WITHOUT INTERMEDIATE SPLICES)
- ④ BRONZE ANGLE SERVICE STOP
- ⑤ VALVE WELL / 1" M.A.R. - 8" PVC / 2" M.A.R. - 10" PVC
- ⑥ REDWOOD OR CONCRETE BLOCK AT TOP OF PIPE ZONE
- ⑦ VALVE WELL CAP / 1" M.A.R. - 8" CAP / 2" M.A.R. - 10" CAP



LEGEND ON PLANS

REVISIONS	APPROVED	DATE	VISTA IRRIGATION DISTRICT	
UPDATED	B. SMITH	03/25/11	1" & 2" MANUAL AIR RELEASES (TYPE B)	<i>Brian Smith</i> 3/25/11
				BRIAN SMITH      DATE
				R.C.E. 39926
				STD. DWG. 2-2